

```
Author: SM4RNA Anders Janis - sm4rna@telia.com.MODIFICATION.NET
ic-1271
ic-1275
ic-2
                      Backside of the Displayborad looks something like below:
ic-2000
ic-2010
ic-207
ic-208
                           r d
ic-210
ic-2100
                           l r d
ic-211
                           r d
ic-22
                           r d
ic-228
ic-229
ic-2320
ic-2330
ic-2340
                                          VFO
ic-2350
                                          ENC-
ic-24
                                          ODER
ic-240
ic-2400
ic-2410
ic-245
ic-25
ic-2500
ic-251
ic-260
ic-27
                      Top left is vertikal row with resistors be seen.
<u>ic-2700</u>
ic-271
                      Beside the resistors to the right a vertical row with diodes is located.
```

<u>ic-2710</u>	
<u>ic-2720</u>	
<u>ic-2725</u>	
<u>ic-275</u>	
<u>ic-28</u>	
<u>ic-2800</u>	
<u>ic-281</u>	
ic-2at	
ic-2gat	
ic-2gxat	
ic-2ia	
<u>ic-2sat</u>	
ic-2se	
<u>ic-2sra</u>	
<u>ic-3</u>	
<u>ic-32</u>	
<u>ic-3200</u>	
<u>ic-3210</u>	
<u>ic-3220</u>	
<u>ic-3230</u>	
<u>ic-338</u>	
<u>ic-37</u>	
<u>ic-3j</u>	
<u>ic-4</u>	
<u>ic-40</u>	
<u>ic-45</u>	
<u>ic-451</u>	
<u>ic-471</u>	

From top is the diodes called D1, D2, D3, HD4, D5, D6, D7, HD8.

- To enable RX 136-174MHz Remove D5.
- To enable RX 420-480MHz Remove D6.
- To enable RX 1240-1320MHz Remove D7.
- To enable narrow FM on 1,2GHz band install a 1SS355 diode at HD8.
- TO enable crossbandrepeater install HD4

To use crossbandrepeater:

- 1. Activate [LOCK]
- 2. Switch off the radio.
- 3. Puch and hold M/S while switch on the radio.

To exit push [LOCK]

(Crossbandrepeat will not be canceled if power is switched off.)

Date: 13-11-2002 User comment From: Chris, DL4JCP

Subject: activate 1750Hz + RX 136-174 + 420-470???

...for DL-Repeater???

Date: 11-10-2003 User comment From: NT9E

Subject: Crossband Repeat mod w/IC-910H

Has anyone done this mod? Does it work well? What diode did you end up installing?

top of page ic-475 add a comment This modification has been read 11089 times. ic-490 ic-4sat ic-4se 22-07-2001 add a comment ic-505 IC-910H mods ic-551 Author: Unknow ic-575 ic-701 ic-703 To modify your rig for: ic-706 ic-706mkii • TX-144 remove R188 (1k) on the display board. 136-174 MHz ic-707 • TX-430 remove R187 (1k) on the display board. 420-480 MHz ic-718 ic-720 • TX-1200 remove R186 (1k) on the display board. 1240-1320 MHz ic-725 Narrow FM mode for 1200MHz install HD8 1SS355 on the display board. ic-728 You do not have to reset the CPU. ic-729 ic-730 **Date:** 18-04-2002 **User comment From:** anonymous ic-735 **Subject:** This mod does not work ic-736 This mod does not work on 910H. ic-737 ic-738 **Date:** 18-07-2002 ic-740 **User comment From:** anonymous ic-7400 Subject: ic 910h ic-745 mod not good for icom ic910h ic-746 power 5watt outsite the band ic-746pro ic-751 **Date: 20-09-2002** From: Mike **User comment** ic-756 Subject: Mod Works, but same as above.. clarification.

<u>ic-756pro</u>
<u>ic-756pro2</u>
<u>ic-761</u>
<u>ic-765</u>
<u>ic-77</u>
<u>ic-775</u>
<u>ic-781</u>
<u>ic-820</u>
<u>ic-821</u>
<u>ic-900</u>
<u>ic-901</u>
<u>ic-910</u>
<u>ic-970</u>
<u>ic-delta1</u>
<u>ic-e90</u>
<u>ic-f3/4</u>
<u>ic-f410</u>
<u>ic-h16</u>
<u>ic-m100</u>
<u>ic-m11</u>
<u>ic-m125</u>
<u>ic-m56</u>
<u>ic-m58</u>
<u>ic-m59</u>
<u>ic-m700</u>
<u>ic-m710</u>
ic-mu2
<u>ic-p2at</u>
_

This mod -WORKS- but as someone else mentioned the power drops down to 7W max immediately outside of the band. I also tried removing resistors further down the "kt" line, only thing this does is make the rig go back to being totally locked again. This is definitely not some kind of bandpass issue, there is some sort of logic that is preventing the rig from going into high power while it is outside of the band. It's almost like the driver stages are functioning but the PA itself is shut off when it's outside of the band. If anyone has any further observations on this mod, or alternative modifications, please contact me directly or post information here.

Date: 10-10-2002 User comment From: XE2VOO

Subject: funciona pero requiere ajuste de menu interno

ESTA MODIFICACION YO LA REALISE Y SI FUNCIONA, ES VERDAD QUE DA POCA POTENCIA PERO SE PUEDE AJUSTAR PARA QUE DE MAS POTENCIA EL TRASMISOR, YO EN LO PERSONAL ESTOY CONTENTO CON LOS RESULTADOS.

VHF 138-143 92W TX

VHF 144-148 105W TX

VHF 149-160 105W-70W TX DEPENDIENDO DEL SWR DE ANTENA EN CUALQUIERA DE ESTOS SEGMENTOS.

UHF 425-430 68W

UHF 431-450 80W

UHF 451.470 80W-65W TX DEPENDIENDO DEL SWR DE ANTENA EN CUALQUIERA DE ESTOS SEGMENTOS. ESTOS SON LOS RESULTADOS DE ESTA MODIFICACION QUE YO OBTUVE.

Date: 12-10-2002 User comment

From: anon

Subject: not working for my 910h

i try this mod also de software mod menu 9 not good for normal power outsite the band

Date: 13-10-2002 User comment From: anon

ic-p2et ic-p3at ic-pcr1000 ic-q7 ic-r1 ic-r10 ic-r2 ic-r3 ic-r7000 ic-r71 ic-r7100 ic-r8500 ic-rp3010 ic-sm2 ic-t2 ic-t22 ic-t3h ic-t7a ic-t7h ic-t8 ic-t81 ic-t90 ic-u16 ic-u2at ic-v200 <u>ic-v8</u> ic-v8000 ic-w21 ic-w2a

Subject: work now prefect

icom 910h works now 100% outside the band thanks

Date: 15-02-2003 User comment From: Rich n2eo

Subject: IC-910H Extended Frequency

Dear Anon I have a fairly new IC-910H. I made the mods for the extended frequency... I removed the 3 resistors on the display board.... I was able to unlock the transmitter outside of the bands... After doing the power override update.. I.E. selecting option 9 on the key board, I am able to get close to 100 watts from 136 - 174 Mhz.

The problem is that what ever I do I can NOT get more than 7 watts on 70Cm.... As somebody else stated this is NOT a band pass issue as you can go right up to 450 MHz and get full 75 watts output... However soon as you go even 5 KHZ above 450 "bang"! The power drops down to 7 or so watts...Do you know of a fix for this problem... 73 "Rich" n2eo

Date: 28-06-2003 User comment From: <u>Uwe</u>

Subject: TX for the Icom IC-910

ic-w2e

ic-w31

ic-w32

ic-x2a

ic-z1a

misc

ps85

<u>sm-20</u>







top of page add a comment

This modification has been read 10225 times.

12-10-2002 <u>add a comment</u>

IC-910 TX power protect software overide

Author: Dave, ZS1SG - j.perry@global.co.za.MODIFICATION.NET

To allow "normal" transmitter power above and below 144-148 MHz.

- 1. Short the CI-V line of the CI-V jack on the back panel, to ground.
- 2. Push and hold the RIT and Sattelite keys whilst turning on power.
- 3. Push 9 key to enter the expanded frequency power set mode.
- 4. Enter the adjustment mode for 144Mhz out-of-band RF power. A wattmeter must be connected.
- 5. Push RIT key to transmit 145.01 automatically. Then rotate the tuning knob to adjust the desired RF power.
- 6. Push RIT key to memorise.

Similar for the 70 and 23 cm bands.

Note that the transmitter power does drop off below 140/425 MHz, and care must be taken not to keep the transmitter keyed in FM mode for long periods as the transistors get hot working into a out-of-resonance stripline.

If the band 136 - 140 is going to be used frequently, then a small adjustment of C659, and the fitting of an additional trimmer capacitor, 5 - 25pF at the antenna end of L657 to ground, and adjusting for max power at 138MHz, will reduce the strain on the PA transistors.

Dave ZS1SG

Date: 25-01-2003 User comment From: kk2ed

Subject: does this work on 450-460

I recall trying the menu setting after shortingthe CI-V lineto ground and holding the RIT/SAT buttons.

I was able to get full power on VHF above 148MHz, but my power still drops to below 50% above 450MHz. I was able to get to the menu option for the 440 out of band setting, but it was though the CPU was overiding my adjustment.

Anyone successful with getting the power increased above 450MHZ?

Thanks

This modification has been read 6685 times.

top of page add a comment

23-11-2003 add a comment

Improved SLOW/FAST AGC response selection for IC-910H

Author: Jean-Jacques - ON7EQ - j.derey@village.uunet.be.MODIFICATION.NET

The IC-910H offers a fast or slow AGC response selection from the front panel, this selection isn't very effective, and in fact AGC is always 'fast'.... In order to improve the selection of the slow response (eliminating the AGC 'pumping' under SSB operation), the R/C timing components of the AGC circuit must be adapted as follows:

- a. Remove power, open top and bottom covers of rig
- b. on the underside, locate the MAIN UNIT PCB (it is on your right side, with the front panel facing to you, and doesn't need to be dismantled)
- c. replace (or just solder as piggyback on) R312 and R914 (22k original value) by 2.2 k resistors, SMD or 1/16watt version.
- d. replace C910 and C306 (originally $22\mu F)$ by $47\mu F/16\nu$ electrolytic type

To locate these components, you will need the service manual which is downloadable from different internet sources as a pdf-document.

Best 73's

Jean-Jacques DE REY - ON7EQ Web http://www.on7eq.com

top of page add a comment

This modification has been read 1181 times.





Have you any tips, trick or modifications you can't find here, please send a mail to me.

Can't you find a modification, then don't e-mail me please. All mododification that i have, is listed on this site.!

Have you problem with www.mods.dk then you can visit the support page.

Start page

